

Sinkhole at Harris Riverfront Park

City workers replaced 20-feet of a 42-inch brick sewer line with a section of reinforced pipe. However, they noticed additional settlement at the sinkhole. After digging, they discovered a failed 12-inch cast-iron sewer main about 30-40 feet down that was pulling sand and other particles into the sewer line. They are now in the process of identifying how much pipe needs to be replaced before the hole can be filled.

